

MAINTENANCE SERVICES



Project Name: ADNOC Offshore ball valve problems

Scope of Work:

- Due to increasing contaminants in process liquid
- Corrosion problems increasing
- Adyard proposed a redesign with inconell overlay
- Balls ground back
- Semi automatic inconell overlay welding
- Grinding and polishing
- Reseating the valve
- Long lasting solution

