

MAINTENANCE SERVICES



Project Name: Ceramic coating for lining pump casing

Scope of Work:

- Modification suggested by Adyard
- ADSSC having major flow and corrosion problems
- Solution proposed ceramic lining
- Running more than 3 years no problems
- Rubber lining also an option for some pumps

