

# MAINTENANCE SERVICES

**Project Name:** OEM poor quality delivery

Scope of Work:

- Tank farm new construction
- 24 20" gate valves supplied OEM
- Tank filled for commissioning 24 hours later tank empty
- Investigation carried out by Adyard
- Incorrect manufacturing and testing OEM
- Adyard supplied full quality report to client

